

July 31, 2017

For more information regarding Whitemore Fire Consultants, Inc., please visit our website at:

www.whitemorefire.com

Nestlé Waters North America Recalls AccuPure Water Dispensers

The Consumer Product Safety Commission in cooperation with Nestlé Waters North America of Stamford, Connecticut has voluntarily issued a recall of the AccuPure floor standing filtration dispensers. The dispensers can overheat and smoke, posing fire and burn hazards.

This recall involves Nestlé Waters AccuPure floor standing filtration dispenser with model #HB215-3G (black) and model #HW215-3G (white). The measure 44.6" tall by 12.5" wide. The units connect to the customer location's plumbing system, draw and filter water from the local system; and then dispense the filtered water through the unit. The upper front panels






of the units have an "AccuPure" logo and an

illuminated clock display. The model number can be found on a white sticker on the back of the dispenser.

Approximately 12,300 units were sold/rented to businesses nationwide from April 2011 through April 2017 as part of individual service contracts with Nestlé Waters. A limited number of units were purchased by these consumers for between \$700 and \$900, depending on the filtration system use. Nestlé Waters does not sell or provide these units at retail.

Consumers should immediately unplug the water dispensers and stop using them. Nestlé Waters is contacting consumers directly to schedule installation of a replace unit. Nestlé Waters has received 15 reports of overheating, including seven of units emitting smoke or catching fire.

For more information please visit: www.readyfresh.com and click on "Safety & Storage" at the bottom of the page.





July 31, 2017


For more information regarding Whitemore Fire Consultants, Inc., please visit our website at:

Outxpro Mosquito Zapper LET Light Bulbs Recalled

The Consumer Product Safety Commission in cooperation with R&D Products, LLC of Willington, Delaware as voluntarily issued a recall of the LED light bulbs. The LED light bulbs can separate from the connector, posing a hazard.




This recall involves all Outzpro 2-in-1 mosquito zapper LED light bulbs. The 10-watt bulb has a white grid housing that measures about 3.1" wide and 6.1" deep. The grid housing has a blue light used to attract insects and an LED light below, for lighting. Item #DYT-80 and "Kniven" is printed on the product's packaging.



The light bulbs were sold exclusive at Amazon.com from July 2016 through August 2016 for about \$20.

For more information, please visit: www.outxpro.com and click on "Recall Information."







July 31, 2017

For more information regarding Whitemore Fire Consultants, Inc., please visit our website at:

www.whitemorefire.com

Or call us at:

952-461-7000

iRover Recalls Self-Balancing Scooters/Hoverboards

The Consumer Product Safety Commission in cooperation with iRover LLC of Fair Lawn, New Jersey has voluntarily issued a recall of the self-balancing scooters/hoverboards. The lithium-ion battery packs in the self-balancing scooters/hoverboards can overheat, posing a risk of smoking catching fire ar



smoking, catching fire and/or exploding.

This recall involves iRover self-balancing scooters, commonly referred to as hoverboards, model numbers 87645 and 87644. The hoverboards have two wheels at either end of a platform and are powered by lithium-ion battery packs. The boards have "iRover" printed on the front outer casing and come in black and white. The model number is listed on the bottom of the unit.

The scooters/hoverboards were sold at Fallas Stores of Los Angeles, California and T.J. Maxx and Marshalls stores nationwide from December 2015 through December 2016 for between \$300 and \$400.

There have been two reports of the battery packs in the recalled self-balancing scooters/hoverboards smoking and overheating. No injuries or property damage have been reported.

Consumers should immediately stop using the recalled scooters/



hoverboards and contact iRover for instructions on returning their hoverboard for a free UL2272-certified replacement unit.

For more information, please visit: www.iroverus.com and click on "Recall Notice.



July 31, 2017

For more information regarding Whitemore Fire Consultants, Inc., please visit our website at:

www.whitemorefire.com

Or call us at:

952-461-7000



YSN Imports Recalls Refillable Propane Cylinders

The Consumer Product Safety Commission in cooperation with YSN Imports d/b/a Flame King of Gardena, California has voluntarily issued a recall of their refillable propane cylinders. The refillable cylinders can leak propane gas, posing fire and explosion hazards.

Approximately 24,000 units were sold in the U.S. and 1,100 in Canada at Ace Hardware, Home Depot, Kamps, Propane Depot, U-Haul and other stores nationwide and online at <u>Amazon.com</u> and other websites from November 2013 through September 2016 for between \$10 and \$15.

This recall involves Flame King, Little Kamper and U-Haul refillable propane cylinders used with outdoor appliances. The serial numbers are printed on the foot ring of the cylinder. For a complete list of serial numbers involved in this recall,

please visit www.cpsc.gov and click on "recalls."

The firm has received two reports of the connecting valve starting to

unscrew from the cylinder. No injuries have been reported.

For more information regarding this recall, please visit: www.flameking.com and click on "Recall Information.





July 31, 2017

For more information regarding
Whitemore Fire Consultants, Inc.,
please visit our website at:

www.whitemorefire.com

Or call us at:

952-461-7000





The Consumer Product Safety Commission in cooperation with Polaris Industries of Medina, Minnesota has voluntarily issued a recall of model year 2015 through 2017 RZR 170 recreational off-highway vehicles. The fuel tank can crack or the wiring harness can overheat or short circuit, posing fuel leak and fire hazards.

This recall involves all model year 2015 through 2017 youth RZR 170 recreational vehicles (ROVs). The recalled ROVs have two seats and were sold in red, blue and white. For model year 2015 ROVs, "Polaris" is printed on the front grill, "RZR" is printed on the rear panel, and "170" is printed on the front panel. For model year 2016 and 2017 ROVs, "Polaris" is printed on the front grill and the rear panel, and "RZR" is printed on the front panel. The VIN is printed on the frame on the driver's side wheel well.

For a complete list of the models and descriptions involved in this recall, please visit www.cpsc.gov.

Consumers should immediately stop using the recalled ROVs and contact Polaris to schedule a free repair. Polaris has received 12 reports of cracked fuel tank necks and 28 reports of burning, smoking, melted and/or shorted wires, including four reports of fires. No injuries have been reported.

Approximately 16,800 units were sold exclusively at Polaris dealers nationwide from February 2015 through July 2017 for between \$4,600 and \$4,800.

For more information please visit: www.polaris.com and click on "Off Road Safety Recalls."